

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 31837 Main Street: VICKSBURG RD **Cross Street: WILLS\_WY** Location: NE **Severity Score: ADA ID: 8018BBFBC038** Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** 50

**Codes/Mitigation Info/Possible Solution** 



**VICKSBURG RD** Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2, R304.5.3

Total Cost: 1850.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	47.0	No	Ramp	Slope (%)	12.1
Yes	Ramp Width (in)	51.0	No	Ramp	XSlope (%)	10.0
N/A	Flare Type LT	N/A	N/A	I/A Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	I/A Flare Slope RT (%)		N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To SE		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.1		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	9.1		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good
THE RESERVE	WALL SERVICE					





