

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10021826 Main Street: BRISTLE TOE LN **Cross Street: N/A** Location: SE ADA ID: 80371D7F7199 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name **BRISTLE TOE LN** Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 None **Remove & Replace Curb Ramp With Two New Directional Ramps or** Equivalent.

Surve

N/A

PRO\

Not

eyor Notes:		
A		
w/ADA:		
ot Found, R304.2.2, F	R304.5.3	
Cost:	\$	3200.00

Total Cost:

Compliance Description Data			pliance Description	Data		
N	N/A	Ramp Length (in)	93.0	No	Ramp Slope (%)	11.7
Υ	⁄es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.7
N	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N	N/A	Shared Landing?	N/A			
N	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
N	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	3.6
		X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	1.8
N	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	0.6	N/A	Clear Space?	N/A
		Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A
1	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
	TOTAL BUT	LAND A STREET,				





