

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29697	Main Sti	reet: NATHANIEL_GLEN_CT	Cross Street: WEDDINGTON_RIDGE_LN				Location:	Ν
ADA ID: 8071AB49BEE2	BEE2 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
		Possible Solutions:	Compliance Description Data			Compliance Description		Data
		Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	9.0
			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.4
	* //		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	3///		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
and the second second			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	D C	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the RIDGE		N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	San star		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
WEDDLA 5	1.1		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
6. William			N/A	Shared Landing?	N/A			
	AL COL	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 a address of a	TEL CUEL OF	Not Found, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Concession of the second secon	·····	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	Carlos and			X Walk 1 Direction	To S		X Walk 2 Direction	N/A
SALA TEAM	AP _ 0		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name WEDDING	TON RIDGE LN	_		X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None			X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

