

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | | |
|---|---------------------------------|---|------------------------|---------------------|
| Intersection ID: 10023486 | Main Street: CIRCUMFERENTIAL_RD | Cross Street: N/A | Location: | NE |
| ADA ID: 80B0D6ACFBE0 | Ramp Type: BlendTrans1 | Initial Pass/Fail: Pass | Overall Compliance: No | Severity Score: 2.5 |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | | |



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.1.4

Total Cost: \$ 3950.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 70.0 | Yes | BlendTrans Slope (%) | 5.0 |
| Yes | Ramp Width (in) | 59.0 | Yes | BlendTrans XSlope (%) | 0.1 |
| N/A | Flare Type LT | None | N/A | Flare Type RT | None |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| Yes | Landing Length (in) | 65.0 | Yes | DWS Provided? | Yes |
| Yes | Landing Width (in) | 59.0 | Yes | DWS Contrast? | Yes |
| No | Landing Slope (%) | 3.7 | Yes | DWS Length (in) | 24.0 |
| No | Landing X Slope (%) | 2.8 | No | DWS Full Width? | No |
| N/A | Landing Curb? (Y/N) | No | Yes | DWS Offset (in) | 1.3 |
| N/A | Shared Landing? | No | | | |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 1.9 |
| Yes | Gutter Lip Ht (in) | 0.0 | No | Gutter X Slope (%) | 4.1 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To S | | X Walk 2 Direction | N/A |
| | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 2.5 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 0.7 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 0.7 | | Clear Space? | Yes |
| | Road X Slope (%) | 2.5 | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | N/A | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | Yes | Curb Slope (%) | 0.6 |

Street 1 Name N/A

Stop Condition-Street 1 None

Street 2 Name N/A

Stop Condition-Street 2 N/A

