

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

$\cdot$ $\cdot$									
Intersection ID: 12086	Main Street: CAMP_GREENE_ST			s Street:	MARLOWE_AV	Location:	NW		
ADA ID: 80B19C5AA0D4	0D4 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Compliance Descriptio					Data
AND CONTRACT OF				<u>00111</u> N/A	Ramp Length (in)	58.0	Yes	Ramp Slope (%)	5.1
AL IS I	A State of the second	Remove & Replace Entire R	amp.	N/A No		58.0 47.5		,	5.1 0.5
A STATE OF A	N. The Mark State	8			Ramp Width (in)			Ramp XSlope (%)	
		8		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
MARLOWE AV		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		- N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	to the second second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A STATE AND		2		N/A	Shared Landing?	N/A			
Des Martin Par		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Ka Bas	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the start the	HAR BERT	,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CAMP GREENE ST	_			X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							1		