

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 17310	Main Street: QUEENS_RD_WEST	Cross Street: SELWYN_AV	Location: NE
ADA ID: 80E0FD5E3638	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:			
	Remove & Replace Entire Ramp.			
Surveyor Notes: N/A	PROW/ADA: R304.2.2, R304.5.3	Compliance	Description	Data
		N/A	Ramp Length (in)	77.0
		Yes	Ramp Width (in)	48.0
		No	Ramp Slope (%)	9.3
		No	Ramp XSlope (%)	4.4
		N/A	Flare Type LT	N/A
		N/A	Flare Slope LT (%)	N/A
		N/A	Flare Traversable LT?	N/A
		N/A	Landing Length (in)	0.0
		N/A	Landing Width (in)	0.0
		N/A	Landing Slope (%)	0.0
		N/A	Landing X Slope (%)	0.0
		N/A	Landing Curb? (Y/N)	N/A
		N/A	Shared Landing?	N/A
		N/A	Gutter Ponding?	0.0
		N/A	Gutter Lip Ht (in)	0.0
		N/A	Painted X Walk1?	Yes
			X Walk 1 Direction	To W
			X Walk 1 Width (in)	113.0
			X Walk 1 Slope (%)	3.8
			X Walk 1 X Slope (%)	0.9
		N/A	Ramp inside XWalk1?	Yes
		N/A	Any Obstructions?	N/A
			Obstruction Type	
		Yes	Surface Condition? (G/P)	Good
		N/A	Curb Slope (%)	17.0

