

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4398 Main Street: AMARANTHUS\_CT Cross Street: BROOKSTONE\_DR Location: N

ADA ID: 80E674F1E8F9 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

| ADA ID: 80E674F1E8F9 Ramp Type: Directional1 |               | Initial I                    | Pass/F  | ail: Fail Overall                       | Complian              | ce: N | o Severity Score:      | 12.5                        |      |  |
|----------------------------------------------|---------------|------------------------------|---------|-----------------------------------------|-----------------------|-------|------------------------|-----------------------------|------|--|
| Codes/Mitigation Info/Possible Solution      |               |                              |         | Field Measurements/Component Compliance |                       |       |                        |                             |      |  |
| <u> </u>                                     |               | Possible Solutions:          |         | Compliance Description                  |                       | Data  | Compliance Description |                             | Data |  |
|                                              | <b>O</b> -    | Remove & Replace Entire Ramp | ).      | N/A                                     | Ramp Length (in)      | 90.0  | N/A                    | Grade Break?                | N/A  |  |
|                                              | DRIVEROUN RO  |                              |         | Yes                                     | Ramp Width (in)       | 52.0  | N/A                    | Grade Break Slope (%)       | 0.0  |  |
| [                                            |               | 1                            |         | No                                      | Ramp Slope (%)        | 9.1   | N/A                    | Grade Break XSlope (%)      | 0.0  |  |
| 1                                            |               |                              |         | Yes                                     | Ramp XSlope (%)       | 0.7   |                        |                             |      |  |
| \_                                           |               |                              |         | N/A                                     | Flare Type LT         | N/A   | N/A                    | Flare Type RT               | N/A  |  |
|                                              |               |                              |         | N/A                                     | Flare Slope LT (%)    | N/A   | N/A                    | Flare Slope RT (%)          | 0.0  |  |
| 18                                           |               | Surveyor Notes:              |         | N/A                                     | Flare Traversable LT? | N/A   | N/A                    | Flare Traversable RT?       | N/A  |  |
| E. E.                                        | CONSTONE DR   | N/A                          |         | N/A                                     | Landing Length (in)   | 0.0   | N/A                    | DWS Provided?               | N/A  |  |
|                                              | 0000          |                              |         | N/A                                     | Landing Width (in)    | 0.0   | N/A                    | DWS Contrast?               | N/A  |  |
| <u></u>                                      |               |                              |         | N/A                                     | Landing Slope (%)     | 0.0   | N/A                    | DWS Length (in)             | N/A  |  |
|                                              |               |                              |         | N/A                                     | Landing X Slope (%)   | 0.0   | N/A                    | DWS Full Width?             | N/A  |  |
|                                              |               | PROW/ADA:                    |         | N/A                                     | Landing Curb? (Y/N)   | N/A   | N/A                    | DWS Offset LT (in)          | N/A  |  |
| 1                                            |               | R304.2.2                     |         | N/A                                     | Shared Landing?       | N/A   | N/A                    | DWS Offset RT (in)          | N/A  |  |
| 1                                            |               |                              |         | N/A                                     | Gutter Ponding?       | 0.0   | N/A                    | Gutter Slope (%)            | N/A  |  |
|                                              | •             |                              |         | N/A                                     | Gutter Lip Ht (in)    | 0.0   | N/A                    | Gutter X Slope (%)          | N/A  |  |
|                                              | <u> </u>      | ]                            |         | N/A                                     | Painted X Walk1?      | No    |                        | Road Slope (%)              | 3.2  |  |
| Street 1 Name                                | AMARANTHUS CT |                              |         |                                         | X Walk 1 Direction    | To SW |                        | Road X Slope (%)            | 2.4  |  |
| Stop Condition-Street 1                      | StopSign      |                              |         |                                         | X Walk 1 Width (in)   | N/A   | l                      | Clear Space?                | N/A  |  |
| Street 2 Name                                | N/A           |                              |         |                                         | X Walk 1 Slope (%)    | 3.2   | N/A                    | Clear Space to XWalk (in)   | N/A  |  |
| Stop Condition-Street 2                      | N/A           |                              |         |                                         | X Walk 1 X Slope (%)  | 2.4   | N/A                    | Storm Grate/Utility Hazard? | N/A  |  |
|                                              |               |                              |         | N/A                                     | Ramp inside XWalk1?   | N/A   |                        | Storm Grate/Utility Type    |      |  |
|                                              |               |                              |         | N/A                                     | Any Obstructions?     | N/A   |                        |                             | N/A  |  |
|                                              |               | Total Cost: \$               | 1600.00 |                                         | Obstruction Type      |       | Yes                    | Surface Condition? (G/P)    | Good |  |
|                                              |               |                              |         |                                         |                       | N/A   | N/A                    | Curb Slope (%)              | N/A  |  |





