

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

14.2

Intersection ID: 19737 Main Street: ABINGDON_RD Cross Street: ARBOR_WY Location: SE

ADA ID: 80EE47F649C4 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 43.75

Compliance Description

Ramp Length (in)

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Compliance Description

Ramp Slope (%)

Data

38.0



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

ABINGDON RD StopSign ARBOR WY None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.5.1, R304.2.2,
R304.5.3

Total Cost:

No Ramp XSlope (%) No Ramp Width (in) 33.0 3.2 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To NW X Walk 2 Direction To SW N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) X Walk 2 Slope (%) 0.9 5.4 X Walk 1 X Slope (%) 0.6 X Walk 2 X Slope (%) 5.2 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 3.8 N/A Clear Space? N/A N/A Road X Slope (%) 2.9 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good







3200.00