

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

10.3

3.2

N/A

No

To SE

N/A

2.0

8.0

N/A

N/A

N/A

N/A

N/A

Good

Intersection ID: 10034513 Main Street: PINEVILLE-MATTHEWS RD Cross Street: N/A Location: NE Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5 ADA ID: 81066F46F211 Ramp Type: PerpDiag

**Codes/Mitigation Info/Possible Solution** 

**ENTRANCE** 

StopSign

None

Field Measurements/Component Compliance

No

No

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Surface Condition? (G/P)

Flare Traversable RT?

Data

65.0

47.0

N/A

No

N/A

0.1

4.4

To SW



Street 1 Name Stop Condition-Street 2 PINEVILLE-MATTHEWS RD Street 2 Name Stop Condition-Street 1

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Compliance Description N/A Ramp Length (in) No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%)

Total Cost: 3200.00

N/A N/A Ramp inside XWalk2? 3.0 N/A Clear Space? N/A 4.2 Clear Space to XWalk (in) Any Obstructions? N/A N/A N/A Storm Grate/Utility Hazard? **Obstruction Type** Storm Grate/Utility Type

N/A

Yes





