


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 31714	Main Street: BLUE_ASH_LN	Cross Street: DEODORA_CEDAR_LN	Location: SW
ADA ID: 819F228A40A9	Ramp Type: NoRamp	Initial Pass/Fail: NoRamp	Overall Compliance: No
		Severity Score: 100	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

PROW/ADA:

N/A

Compliance	Description	Data
------------	-------------	------

Total Cost: \$ 1500.00

