

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

			•									
Intersection ID: N/A	Main Street: PROVIDENCE_RD				Cross	Street:	BERKELEY_GRE	Location:	SW			
ADA ID: 81D35147727	1 Ramp T	Ramp Type: Perp				Pass/Fa	ail: Fail Over	o Severity Score:	72.5			
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
1 C 1 1 2 1	Possible Solutions:								Compliance Description Data			
	他们的 在1995年的第三	Remove & Replace Entire Ra		Ram	n	N/A	Ramp Length (in)	81.5	1	Ramp Slope (%)	13.1	
				lann	γ.	No	Ramp Width (in)	25.0		Ramp XSlope (%)	5.6	
		3				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Later 1	· · · · · · · · · · · · · · ·	2				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A	
5 4608 V	82					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	W Con					N/A	Landing Length (in)	N/A		DWS Provided?	N/A	
		Surveyor Notes:				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A				N/A	Landing X Slope (%)	N/A		DWS Full Width?	N/A	
						N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A	
and the second	1 0 11 0 1					N/A	Shared Landing?	N/A		2		
		PROW/ADA:				N/A	Gutter Ponding?	N/A		Gutter Slope (%)	N/A	
A COLORED A REAL	not the R	6	D204 5 4 D204	っ っ		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A	
	A STREET, STRE	R304.5.3	R304.5.1, R304		1	N/A	Painted X Walk1?	No		Painted X Walk2?	N/A	
CH2	11-1-1-1-1-10	1004.0.0				11/4	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
	No. of the Prove					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	BERKELEY GREENE DR					N/A	X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	N/A	
							,	3.2 4.5		• • • •	N/A N/A	
Stop Condition-Street 2 Street 2 Name	StopSign					NI/A	X Walk 1 X Slope (%)			X Walk 2 X Slope (%)		
	N/A					N/A	Ramp inside XWalk1?			Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A						Road Slope (%)	N/A		Clear Space?	N/A	
							Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
						N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:		\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
								N/A	1		N/A	