

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48001 Main Street: LARKMEAD\_FOREST\_DR Cross Street: CLYMER\_CT Location: SW

ADA ID: 81E3AFAE2C77 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name LARKMEAD FOREST DR
Stop Condition-Street 2 StopSign
Street 2 Name CLYMER CT
Stop Condition-Street 1 None

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Yes N/A Ramp Length (in) 71.5 Ramp Slope (%) 6.1 Yes Ramp XSlope (%) No Ramp Width (in) 44.0 0.4 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To E X Walk 2 Direction To N N/A N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 0.9 X Walk 2 Slope (%) 4.8 X Walk 2 X Slope (%) X Walk 1 X Slope (%) 2.7 0.5 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 0.1 N/A Clear Space? N/A N/A Road X Slope (%) 2.3 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





