


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 31467	Main Street: BULLOCK_DR	Cross Street: SENEY_DR	Location: SW
ADA ID: 81F781CBB09B	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
 <div>Street 1 Name<div>BULLOCK DR</div></div> <div>Stop Condition-Street 2<div>StopSign</div></div> <div>Street 2 Name<div>SENEY DR</div></div> <div>Stop Condition-Street 1<div>None</div></div>	Possible Solutions:  <b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	<b>Compliance</b>	<b>Description</b>	<b>Data</b>
			N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	7.0
			No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	6.0
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	N/A
		N/A	Shared Landing?	N/A				
		N/A	Gutter Ponding?	N/A	N/A	N/A	Gutter Slope (%)	N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A	N/A	Painted X Walk2?	No
			X Walk 1 Direction	To E			X Walk 2 Direction	To N
		N/A	X Walk 1 Width (in)	N/A	N/A	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	5.5			X Walk 2 Slope (%)	1.3
			X Walk 1 X Slope (%)	2.2			X Walk 2 X Slope (%)	5.5
		N/A	Ramp inside XWalk1?	N/A	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	4.4	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	3.5	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	N/A	Storm Grate/Utility Hazard?	N/A
			Obstruction Type				Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 3200.00						

