

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

59.0

60.5

8.8

3.6

N/A

Good

14.6

Intersection ID: N/A Main Street: PENCE\_POND\_LN Cross Street: PENCE\_RD Location: NW

ADA ID: 820F342212BE Ramp Type: Combination2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp XSlope LT (%)

N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Surface Condition? (G/P)

Curb Slope (%)

Data

N/A

N/A

N/A

N/A No



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

StopSign PENCE POND LN N/A N/A

"	1 CSSIDIC COIDLIOII
-	Possible Solutions:
	Remove & Replace Entire Ramp.
1	
Section 2	
	Surveyor Notes:
THE PERSON	N/A
	N/A
The said	
	PROW/ADA:
N	Not Found, R304.5.1, R304.5.3,
	R304.3.2
V	



Total Cost:



1600.00

N/A	Ramp Length (in)	69.5	Yes	Ramp Slope (%)	5.0
No	Ramp Width (in)	30.0	No	Ramp XSlope (%)	2.1
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
	The Assert			Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	

Yes