

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31542	Main Street: ALMORA DR			Cross	Cross Street: OLD_PLANK_RD				Location:	NW
	Main Street: ALMORA_DR									
ADA ID: 821B77DB7B03 Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:			Comp	liance Description	Data	Comp	liance Description	Data
		Remove & Replace Entire	e Ram	р.	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.3
	12	_			No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	2.6
	3				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	* · ·				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ST 1000	ACT				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1 Carlos				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
m th		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Plan b.					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second sec					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Contract of the second second	A CASING	Not Found, R304.5.1, R3	04.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Star P						X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ALMORA DR					X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

