


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 23983	Main Street: DEHAVILLAND_DR	Cross Street: FOKKER_PL	Location: NE
ADA ID: 822663743095	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	<b>Compliance</b>
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		<b>Description</b>		<b>Data</b>	<b>Description</b>
<p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>R304.2.2</b></p>			N/A	Ramp Length (in)	47.0	No
			Yes	Ramp Width (in)	48.0	Yes
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To NW	X Walk 2 Direction
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	3.3	X Walk 2 Slope (%)
				X Walk 1 X Slope (%)	0.1	X Walk 2 X Slope (%)
			N/A	Ramp inside XWalk1?	N/A	N/A
				Road Slope (%)	0.7	N/A
				Road X Slope (%)	3.3	N/A
			N/A	Any Obstructions?	N/A	N/A
				Obstruction Type		Storm Grate/Utility Hazard?
						Storm Grate/Utility Type
					N/A	N/A
			Yes	Surface Condition? (G/P)	Good	

Total Cost: \$ 3200.00

