

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11684 Main Street: CARLYLE_DR Cross Street: WILSON_AV Location: S

ADA ID: 8249AFC14874 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution



Street 1 Name	WILSON AV
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	
Remove & Replace Entire Ramp.	I
	!
1	
	ı
Surveyor Notes:	ı
N/A	ı
in the second se	
PROW/ADA:	
Not Found, R304.5.1, R304.2.2	ı
	I
	ı

T		Ę.



Total Cost:



1850.00

Field Measurements/Component Compliance						
Compli	ance Description	Data	Compl	iance Description	Data	
N/A	Ramp Length (in)	35.0	No	Ramp Slope (%)	8.4	
No	Ramp Width (in)	43.5	Yes	Ramp XSlope (%)	1.6	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	