

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 7243	Main Street: N_GRAHAM_ST	Cross Street: S_I-85_EXIT_40_RA	Location: NE
ADA ID: 824BB83592E2	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0	

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R305.1.4, R305.2**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	202.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	71.0	Yes	Grade Break Slope (%)	4.5
Yes	Ramp Slope (%)	5.8	Yes	Grade Break XSlope (%)	1.5
Yes	Ramp XSlope (%)	0.0			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	51.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	72.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.9	No	DWS Length (in)	23.5
Yes	Landing X Slope (%)	1.7	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	No	DWS Offset LT (in)	5.0
N/A	Shared Landing?	No	No	DWS Offset RT (in)	120.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.9
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	2.6
N/A	Painted X Walk1?	Yes		Road Slope (%)	0.6
	X Walk 1 Direction	To SW		Road X Slope (%)	7.0
	X Walk 1 Width (in)	109.0		Clear Space?	Yes
	X Walk 1 Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	7.0	Yes	Storm Grate/Utility Hazard?	No
Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	36.6

Total Cost: \$ 1600.00

