

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			•		. /						
Intersection ID: 48587	Main Street: STONEY_CREEK_LN				Cross Street: UNIVERSITY_CITY_BV				Location:	NW	
ADA ID: 825FE2251246	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Compliance:				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	Possible Solutions:				Compliance Description			Data Compliance Description			
	Inter the state of the	Remove & Replace En	tire Ra	mp.	N/A	Ramp Length LT (in)	16.0	N/A	Ramp Length RT (in)	27.0	
	A A A A A A A A	•		•	Yes	Ramp Width LT (in)	72.0	Yes	Ramp Width RT (in)	72.0	
and and a	- West				Yes	Ramp Slope LT (%)	1.4	Yes	Ramp Slope RT (%)	4.3	
is a local start	a transferration				No	Ramp XSlope LT (%)	2.6	Yes	Ramp XSlope RT (%)	2.0	
The second of th	g I				N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	3.9	
and a plant the	O CANANA S				No	Ramp Width (in)	45.5	No	Ramp XSlope (%)	2.8	
111		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
<mark>6.</mark>	B & B	LT RP < 5%, RT RP < 5	%		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
h					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
UNIVERSITY_CITY_EX					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
UNIVERSION					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
1 1	1 Land	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
T North The	.a.	Not Found, R304.5.1,	R304.5	.3	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
A state	Filmen				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	STONEY CREEK LN				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		1 Stand and	A ve de	Star Martin		1 Alexandre		N/A	Any Obstruction?	N/A	
	STOP				The states				Obstruction Type		
			Na.	W. I.	C. Contas					N/A	
								N/A	Storm Grate/Utility Hazard?	N/A	
	m								Storm Grate/Utility Type		
					the part of the second			I I		NI/A	

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 13.7





