

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

53.0

70.0

10.8

4.4

8.7

3.4

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Cross Street: CLAY AV Location: Intersection ID: 10857 Main Street: ALICE AV Ν Initial Pass/Fail: Fail **Overall Compliance: No ADA ID: 8295B2CEC1E2** Ramp Type: Combination1 Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

No

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

D14/0 E 11 14/2 1/1 0

Curb Slope (%)

Flare Traversable RT?

Data

70.0

42.0

0.4 No

5.6

71.0 No

47.0

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



None Street 1 Name Stop Condition-Street 1 **CLAY AV** N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. No Yes No N/A No Surveyor Notes: N/A LT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A R304.5.1, R304.5.1, R304.2.2, N/A R304.5.3, R304.3.2 N/A N/A N/A N/A N/A



Total Cost:



N/A

1800.00

N/A	N/A	DWS Full Width?	N/A
N/A	N/A	DWS Offset (in)	N/A
N/A			
N/A	N/A	Gutter Slope (%)	N/A
N/A	N/A	Gutter X Slope (%)	N/A
No	N/A	Painted X Walk2?	N/A
To W		X Walk 2 Direction	N/A
N/A		X Walk 2 Width (in)	N/A
2.8		X Walk 2 Slope (%)	N/A
2.7		X Walk 2 X Slope (%)	N/A
N/A	N/A	Ramp inside XWalk2?	N/A
N/A		Clear Space?	N/A
N/A	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstruction?	N/A
		Obstruction Type	
			N/A
	N/A	Storm Grate/Utility Hazard?	N/A
		Storm Grate/Utility Type	
			N/A
	Yes	Surface Condition? (G/P)	Good
	N/A N/A N/A No To W N/A 2.8 2.7 N/A	N/A N/A N/A N/A N/A N/A N/A N/A TO W N/A 2.8 2.7 N/A	N/A