## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 1001992	21 Main Street: ARDREY_KELL_RD			Street:	N/A	Location:	NW		
ADA ID: 82F3D4E636E3	Ramp Ty	Ramp Type: BlendTrans2			ail: Fail Overall C	o Severity Score:	8.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
G AL		Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ra	mp With	N/A	Ramp Length (in)	80.0	Yes	BlendTrans Slope (%)	4.3
		Two New Directional Ramps Equivalent.		No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	1.6
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	A a B			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<u>, 6</u>		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	t.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
ARDREY KELL RD				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		· · ·	
ALL STR. MARK	5	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.5.1				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
TTREE DE LA COMPANY					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE	-			X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.0		Clear Space?	N/A
					Road X Slope (%)	2.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

19.3