cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23175	ersection ID: 23175 Main Street: ALEXANDER_HALL_DR			Street:	ALEXANDER_RD	Location:	NE		
ADA ID: 8317AF1F9571	F Ramp Ty	Ramp Type: PerpDiag			itial Pass/Fail: Fail Overall Complia			o Severity Score:	25
	Codes/Mitigation Info		Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
A . MAK		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	/ith	N/A	Ramp Length (in)	58.0	Yes	Ramp Slope (%)	5.4
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.7
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	A CONTRACTOR			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Company of Canada			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
SOLL IF	and the second second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	1. Start	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	5 RD	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6. ANDERS				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
All Burn				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Mar 1	and the state			N/A	Shared Landing?	N/A			
	and the second second	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A Street C	and and a state			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
a state and	V.V. C. R.				X Walk 1 Direction	To SW		X Walk 2 Direction	To S
a set of				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ALEXANDER HALL DR	_			X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	7.3
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	6.1		X Walk 2 X Slope (%)	0.5
Street 2 Name	ALEXANDER RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	3.8	N/A	Clear Space?	N/A
					Road X Slope (%)	6.8	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good

