## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10038044	Main Street: SHOPTON RD			Street:	N/A	Location:	S		
									12.5
									12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Storiot 20		Possible Solutions:					Comp	liance Description	Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	5.8
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		2		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
P HARDEN INC.				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the statement of the st				N/A	Shared Landing?	N/A			
and all the	AL AL	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
ATTACK AND AND				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	S. www.				X Walk 1 Direction	To SE		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	3.2
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	6.8		X Walk 2 X Slope (%)	1.9
Street 2 Name	Shopton			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	4.4	N/A	Clear Space?	N/A
					Road X Slope (%)	6.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

