


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 53288	Main Street: PROSPERITY_CHURCH_RD	Cross Street: ROBERT_HELMS_RD	Location: S
ADA ID: 8326CF95EED7	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		<b>Remove &amp; Replace Entire Ramp.</b>						
	Surveyor Notes:		<b>N/A</b>						
	PROW/ADA:		<b>R304.2.2</b>						
	Street 1 Name		<b>PROSPERITY CHURCH RD</b>						
	Stop Condition-Street 2		<b>YieldSign</b>						
	Street 2 Name		<b>N/A</b>						
	Stop Condition-Street 1		<b>N/A</b>						
	Total Cost:		<b>\$ 1850.00</b>						

