cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040845	Main Street: WAKEFIELD_DR		Cross	Street:	N/A	Location:	E		
ADA ID: 83956E5D51AD	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Co			Comp	Compliance Description Data	
		Remove & Replace Curb Ramp \	With	N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	5.5
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	9.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
MAKEFIELD		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A TAL				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A STREET, AND A ST	Jane -			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and shake there		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second second				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
All and the second s	Eller - Take				X Walk 1 Direction	To W		X Walk 2 Direction	To S
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	9.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	5.2		X Walk 2 X Slope (%)	7.1
Street 2 Name	WAKEFIELD DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	7.6	N/A	Clear Space?	N/A
					Road X Slope (%)	2.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
1							•		

s Surface Condition? (G/P)

Good

