

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · ·									
Intersection ID: 32121	n ID: 32121 Main Street: ALEXA_RD			Street:	PROVIDENCE_RD	Location:	NE		
ADA ID: 83DA17F72256	2256 Ramp Type: Perp			Pass/Fa	ail: Fail Overall	o Severity Score:	33.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A B COM TO	0	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Entire Ramp	).	N/A	Ramp Length (in)	83.0	No	Ramp Slope (%)	11.0
				No	Ramp Width (in)	39.0	No	Ramp XSlope (%)	5.4
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	•			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1 mil			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	State of			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	-	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6 B NEXA RD	10 211 2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A BAR	A CAN			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
- B - DIL	Constant			N/A	Shared Landing?	N/A			
· E B TRATION		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
6 Charles	A REAL PRIME	Not Found, R304.5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	14. S. W. 19.	R304.5.3		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	· · · · · · · · · · · · · · · · · · ·				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	. A. A Provident			N/A	X Walk 1 Width (in)	104.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ALEXA RD				X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

