


Intersection ID: 10040568		Main Street: W_ARROWWOOD_RD		Cross Street: N/A		Location:		SW	
ADA ID: 83FD0FA0F7F5		Ramp Type: PerpDiag		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance		Description		Data	
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length (in)		61.0	
				Yes		Ramp Width (in)		48.0	
				N/A		Flare Type LT		N/A	
				N/A		Flare Slope LT (%)		N/A	
				N/A		Flare Traversable LT?		N/A	
				N/A		Landing Length (in)		N/A	
				N/A		Landing Width (in)		N/A	
				N/A		Landing Slope (%)		N/A	
				N/A		Landing X Slope (%)		N/A	
Surveyor Notes: N/A				N/A		Flare Slope RT (%)		N/A	
				N/A		Flare Traversable RT?		N/A	
				N/A		DWS Provided?		N/A	
				N/A		DWS Contrast?		N/A	
				N/A		DWS Length (in)		N/A	
				N/A		DWS Full Width?		N/A	
				N/A		DWS Offset (in)		N/A	
				N/A					
				N/A		Gutter Ponding?		N/A	
				N/A		Gutter Lip Ht (in)		N/A	
PROW/ADA: R304.5.3				N/A		Painted X Walk2?		No	
						X Walk 1 Direction		To SE	
				N/A		X Walk 1 Width (in)		N/A	
						X Walk 1 Slope (%)		3.4	
						X Walk 1 X Slope (%)		6.0	
				N/A		Ramp inside XWalk1?		N/A	
						Road Slope (%)		8.9	
						Road X Slope (%)		0.9	
				N/A		Any Obstructions?		N/A	
						Obstruction Type			
				N/A				N/A	
				Yes		Surface Condition? (G/P)		Good	

