

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

62.5

96.0

5.0

2.9

3.2

5.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/Δ

Intersection ID: 21398 Main Street: KINGS\_PARADE\_BV Cross Street: CAMBRIDGE\_BELTWAY\_DR Location: SE

ADA ID: 841E7EBC0BAE Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

No

Yes

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

N/A

Yes

Yes

No

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slone (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

47.0

98.0

11.2

0.9

97.5

44.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A



Street 1 Name

Stop Condition-Street 1

Street 2 Name

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.3.2, R304.5.3



Total Cost:



1800.00

N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	5.3		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	5.9		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
TX			N/A	Any Obstruction?	N/A
				Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	147.1
					N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	12.5

