

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Intersection ID: 30125 Main Street: CLOONEY_LN Cross Street: RUMPLE_RD Location: E

ADA ID: 844A62E26BDC Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Total Cost:

Field Measurements/Component Compliance

Data Compliance Description



Street 1 Name	CLOONEY LN
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Comp	liance	Description	
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)		
·	No	Ram	Ramp Width (in)	
	N/A	Flare	Type LT	
	N/A	Flare	Slope LT (%)	
	N/A	Flare	Traversable LT	
	N/A	Land	ing Length (in)	
Surveyor Notes:	N/A	Land	Landing Width (in)	
N/A	N/A	Land	Landing Slope (%)	
	N/A	Land	ing X Slope (%)	
	N/A	Land	ing Curb? (Y/N)	
	N/A	Shar	ed Landing?	
PROW/ADA:	N/A	Gutte	er Ponding?	
Not Found, R304.5.1	N/A	Gutte	Gutter Lip Ht (in)	
	N/A	Paint	ed X Walk1?	
		X Wa	alk 1 Direction	
	N/A	X Wa	alk 1 Width (in)	
		X Wa	alk 1 Slope (%)	
		X Wa	alk 1 X Slope (%	
	N/A	Ram	p inside XWalk1	
		_		

LOWE .		



1850.00

ООПІР	nunce Description	Dutu	ООПІР	nunce Description	Dutu
N/A	Ramp Length (in)	50.0	Yes	Ramp Slope (%)	8.1
No	Ramp Width (in)	43.0	Yes	Ramp XSlope (%)	1.3
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good