

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

54.5

48.0

5.5

4.0

3.0

1.4

N/A

N/A

Good

11.2

Intersection ID: 6469Main Street: OLD_PLANK_RDCross Street: DALE_AVLocation: NWADA ID: 84A3F08E3E19Ramp Type: Combination1Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

No

No

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

Yes

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Ramp XSlope RT (%)

Surface Condition? (G/P)

Curb Slope (%)

Data

46.5

48.0

9.2

3.7

48.0

43.0 Yes

N/A N/A



Street 1 Name

Stop Condition-Street 1

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.3.2, R304.5.3

Total Cost:



1800.00

riare Type LT	IN/A	IN/A	riale Type KT	IN/F
Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
X Walk 1 Direction	To S		X Walk 2 Direction	N/A
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	N/A
X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	N/A		Clear Space?	N/A
Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
A COURT OF THE		N/A	Any Obstruction?	N/A
			Obstruction Type	
				N/A
The state of the s		N/A	Storm Grate/Utility Hazard?	N/A
Market Property Control			Storm Grate/Utility Type	
	Flare Slope LT (%) Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%)	Flare Slope LT (%) Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? N/A Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? N/A Road Slope (%) N/A	Flare Slope LT (%) Flare Traversable LT? Landing Length (in) Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Slope (%) X Walk 1 Slope (%) X Walk 1 X Slope (%) Road X Slope (%) N/A	Flare Slope LT (%) Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Slope (%) X Walk 1 X Slope (%) X Walk 2 X Slope (%

Yes

