


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 44477	Main Street: AINSWORTH_ST	Cross Street: WESTHOPE_ST	Location: NE
ADA ID: 84B6474DDD6A	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 36.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
 <p>Street 1 Name AINSWORTH ST</p> <p>Stop Condition-Street 2 None</p> <p>Street 2 Name WESTHOPE ST</p> <p>Stop Condition-Street 1 StopSign</p>	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Slope (%)	6.1
			No	Ramp XSlope (%)	2.5
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Slope (%)	N/A
			N/A	Gutter X Slope (%)	N/A
			No	Painted X Walk2?	No
			To W	X Walk 2 Direction	To S
			N/A	X Walk 2 Width (in)	N/A
			2.2	X Walk 2 Slope (%)	3.1
			2.5	X Walk 2 X Slope (%)	2.6
			N/A	Ramp inside XWalk2?	N/A
			1.5	Clear Space?	N/A
			4.2	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			N/A	Surface Condition? (G/P)	Good
Surveyor Notes:					
N/A					
PROW/ADA:					
Not Found, R304.5.1, R304.5.3					
Total Cost:		\$ 3200.00			

