

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12426	Main Street: KENWOOD_AV	Cross Street: MIDWOOD_PL	Location: SW
ADA ID: 84CC26A78FE1	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 2.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.
Remove & Replace Gutter.**

Surveyor Notes:

N/A

PROW/ADA:

**R304.2.2-Perp, R304.3.2-Para,
R304.5.3, R305.1.4**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	47.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	50.0	Yes	Grade Break Slope (%)	3.2
Yes	Ramp Slope (%)	5.3	Yes	Grade Break XSlope (%)	0.1
Yes	Ramp XSlope (%)	1.2			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Yes	Landing Length (in)	61.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	58.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	2.8	Yes	DWS Length (in)	25.5
No	Landing X Slope (%)	2.3	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	13.0
N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	2.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.0
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	6.4
N/A	Painted X Walk1?	No		Road Slope (%)	6.4
	X Walk 1 Direction	To E		Road X Slope (%)	0.0
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	6.4	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	0.0	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	0.4

Total Cost: \$ 2350.00

