cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 21910	Main Str	eet: CARMEL RD	Cross	Cross Street: COLONY RD				Location:	w
ADA ID: 84DDCC20AD26	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Compliance Description Data					
		Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	10.9
				N/A No	Ramp Width (in)	35.0	Yes	Ramp XSlope (%)	2.7
ANT I STATE A				N/A	,	35.0 N/A	N/A	,	2.7 N/A
and the second s					Flare Type LT			Flare Type RT	
and the states				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
NY IN TO A				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Carle Mary C.		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Sector Sector				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	125 170			N/A	Shared Landing?	N/A			
sis shall be	6. 3 1	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.2	2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		, ,		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	ALCONT .				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	101.0	N/A	X Walk 2 Width (in)	103.0
Street 1 Name	CARMEL RD	-			X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	6.6
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	5.6		X Walk 2 X Slope (%)	0.8
Street 2 Name	COLONY RD			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	Signal				Road Slope (%)	3.8	N/A	Clear Space?	N/A
1 -	- 5 -				Road X Slope (%)	5.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.0 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		ισταί σοστ. ψ	5200.00			N/A		Storm Oraco Otimey Type	N/A
						IN/A			IN/A

