


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 45491	Main Street: GRASSY_CROPS_RD	Cross Street: TRIANGLE_PARK_RD	Location: SW
ADA ID: 851092D9C12B	Ramp Type: Combination1Diag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 0	

Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			N/A	Ramp Length LT (in)	27.0	N/A	Ramp Length RT (in)	45.0
				No	Ramp Width LT (in)	47.0	No	Ramp Width RT (in)	47.0
				Yes	Ramp Slope LT (%)	5.0	Yes	Ramp Slope RT (%)	5.0
				No	Ramp XSlope LT (%)	4.2	No	Ramp XSlope RT (%)	4.7
				N/A	Ramp Length (in)	71.0	No	Ramp Slope (%)	11.7
				No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	3.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Surveyor Notes:			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To E		X Walk 2 Direction	To N	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
				X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	3.0	
				X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	0.7	
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
				Road Slope (%)	4.6		Clear Space?	N/A	
				Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A	
						N/A	Any Obstruction?	N/A	
							Obstruction Type	N/A	
						N/A	Storm Grate/Utility Hazard?	N/A	
							Storm Grate/Utility Type	N/A	
						Yes	Surface Condition? (G/P)	Good	
							Curb Slope (%)	16.8	
PROW/ADA:									
			Not Found, R304.5.1, R304.5.1, R304.2.2, R304.5.3						
Total Cost:			\$ 3200.00						
Street 1 Name			StopSign						
Stop Condition-Street 1			TRIANGLE PARK RD						
Street 2 Name			None						
Stop Condition-Street 2			GRASSY CROPS RD						
