cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			•	• •						
Intersection ID: 20278	Main Str	Main Street: ARCHDALE_DR			Cross Street: MONTPELIER_RD			Location:		
ADA ID: 852426E74065	Ramp Ty	Ramp Type: Combination1Diag			Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score:		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
1 HOLES HALL	Stell WILL	Possible Solutions:		Compliance Descrip		Data Compli		ance Description	Data	
Find the	UTHUR TO ADA	Remove & Replace (Curb Ramp With	N/A	Ramp Length LT (in)	56.0	N/A	Ramp Length RT (in)	50.0	
	ALL SALE STOP	Two New Directional	•	No	Ramp Width LT (in)	45.0	No	Ramp Width RT (in)	44.0	
		Equivalent.		Yes	Ramp Slope LT (%)	5.1	Yes	Ramp Slope RT (%)	6.0	
	A CONT			No	Ramp XSlope LT (%)	2.7	Yes	Ramp XSlope RT (%)	1.6	
10 th 100				N/A	Ramp Length (in)	29.0	Yes	Ramp Slope (%)	5.2	
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.6	
122	1	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the test	1 102	N/A		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
6 0 K				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	CARD IN			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
till a c.		PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
Tor.		Not Found, R304.5.1	R304.5.3	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
2 /		,	,	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None	-		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	ARCHDALE DR			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	StopSign				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
Stop Condition-Street 2	MONTPELIER RD				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
					X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	2.5	
					X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	2.0	
		Total Cost:	\$ 3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
					Road Slope (%)	0.4		Clear Space?	N/A	
					Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A	
				et - et	for the second		N/A	Any Obstruction?	N/A	
								Obstruction Type		
								- •	N/A	
							N/A	Storm Grate/Utility Hazard?	N/A	
								Storm Grate/Utility Type	11/25	

утур Surface Condition? (G/P) Yes Good Curb Slope (%) 18.4

N/A