## cole

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Intersection ID: N/A Main Street: PINEVILLE-MATTHEWS_RD Cross Street: N/A							Location:	SE
ADA ID: 854489EC0	56B Ramp Ty	ype: PerpDiag	Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
The method		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	lith	N/A	Ramp Length (in)	153.0	No	Ramp Slope (%)	10.9
E Pail				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.0
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Harder and Britania	6.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	E MATTRIEWS RD	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	the state of the			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
5 B	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
and the second s				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
PROW/ADA:				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		·····, ·····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To N		X Walk 2 Direction	To W
	The later has			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PINEVILLE-MATTHEWS RD				X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	1.2
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	2.5
Street 2 Name	ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.8	N/A	Clear Space?	N/A
					Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good