

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7914 Main Street: DAVID_AV Cross Street: SWIFT_ARROW_LN Location: N/A

ADA ID: 855E911FE5C7 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Swift Arrow LN
Stop Condition-Street 2
None
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:	Con
Remove & Replace Entire Ramp.	N/A
·	No
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.1	N/A
	N/A
	N/A
	N/A

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	5.3	
No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	1.4	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	4.0	N/A	Clear Space?	N/A	
	Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
P. W. Hall	W. W. W. W. Company					





