Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Intersection ID: 10014252	**Main Street: PARKWOOD_AV**	**Cross Street: N/A**	**Location:**	**S**
ADA ID: 8600DB8C7BE1	**Ramp Type: Combination1Diag**	**Initial Pass/Fail: Fail**	**Overall Compliance: No**	**Severity Score: 0**

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

RP < 5%

PROW/ADA:

R304.3.2

Street 1 Name — **StopSign**
Stop Condition-Street 1 — **E 17TH ST**
Street 2 Name — **None**
Stop Condition-Street 2 — **PARKWOOD AV**

Total Cost: **$ 3200.00**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	51.0	N/A	Ramp Length RT (in)	44.0
Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	59.0
Yes	Ramp Slope LT (%)	7.9	No	Ramp Slope RT (%)	9.7
Yes	Ramp XSlope LT (%)	1.0	Yes	Ramp XSlope RT (%)	0.1
N/A	Ramp Length (in)	24.0	Yes	Ramp Slope (%)	3.1
Yes	Ramp Width (in)	60.0	Yes	Ramp XSlope (%)	1.3
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	2.1
	X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	0.7
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.1		Clear Space?	N/A
	Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	3.8