




# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)



Intersection ID: 6159	Main Street: ORR_ST	Cross Street: GRAYPARK_DR	Location: NE
ADA ID: 86018E18E472	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 0			

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>Yes</b>	Ramp Length (in)	48.0
	<b>Remove &amp; Replace Gutter.</b>		<b>Yes</b>	Ramp Width (in)	48.0
			<b>N/A</b>	Flare Type LT	Sloped
			<b>N/A</b>	Flare Slope LT (%)	5.9
			<b>N/A</b>	Flare Traversable LT?	No
			<b>Yes</b>	Landing Length (in)	48.0
			<b>Yes</b>	Landing Width (in)	48.0
			<b>No</b>	Landing Slope (%)	2.5
			<b>Yes</b>	Landing X Slope (%)	0.9
Surveyor Notes:  <b>N/A</b>			<b>N/A</b>	Flare Type RT	N/A
			<b>N/A</b>	Flare Slope RT (%)	3.6
			<b>N/A</b>	Flare Traversable RT?	No
			<b>Yes</b>	DWS Provided?	Yes
			<b>Yes</b>	DWS Contrast?	Yes
			<b>Yes</b>	DWS Length (in)	24.5
			<b>Yes</b>	DWS Full Width?	Yes
			<b>No</b>	DWS Offset (in)	3.0
			<b>N/A</b>	Shared Landing?	No
			<b>Yes</b>	Gutter Ponding?	No
PROW/ADA:  <b>Not Found, R304.2.2-Perp, R304.3.2-Para, R305.2, R304.5.4</b>			<b>Yes</b>	Gutter Lip Ht (in)	0.0
			<b>N/A</b>	Painted X Walk1?	No
				X Walk 1 Direction	To W
			<b>N/A</b>	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	3.5
				X Walk 1 X Slope (%)	1.3
			<b>N/A</b>	Ramp inside XWalk1?	N/A
			<b>N/A</b>	Road Slope (%)	N/A
			<b>N/A</b>	Road X Slope (%)	N/A
			<b>Yes</b>	Any Obstructions?	No
Total Cost: \$ 2600.00				Obstruction Type	
			<b>N/A</b>		
			<b>Yes</b>	Surface Condition? (G/P)	Good

