


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 4066	Main Street: W_MALLARD_CREEK_CHURCH_RD	Cross Street: DAVID_TAYLOR_DR	Location: E
ADA ID: 861435A1F012	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 15.25

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance							
	Possible Solutions:	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.							
	Surveyor Notes:	N/A							
	PROW/ADA:	Not Found, R304.5.3, R304.2.2-Perp, R304.3.2-Para, R305.1.4, R305.2, R302.7.2, R304.5.4							
	Street 1 Name	DAVID TAYLOR DR							
	Stop Condition-Street 2	StopSign							
	Street 2 Name	MALLARD CREEK CHURCH RD							
	Stop Condition-Street 1	None							
	Total Cost:	\$	3950.00						

