

ADA ID: 8681A6BD9F46

Access Compliance Report Public Rights-of-Way (Curb Ramps)



8.75

Data

7.1

1.1

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Severity Score:

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Flare Traversable RT?

Flare Type RT

Main Street: POLLYS GARDEN CR Ε Intersection ID: 48957 Cross Street: FRANKLIN SQUARE RD Location: **Overall Compliance: No**

Initial Pass/Fail: Fail

Flare Slope LT (%) Flare Traversable LT?

Codes/Mitigation Info/Possible Solution

Ramp Type: Perp

Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Data

47.0

47.5

N/A



FRANKLIN SQUARE RD Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	Compli	iance	Description
Remove & Replace Entire Ramp.	N/A	No Ramp Width (in) N/A Flare Type LT	
·	No		
	N/A		
	N/A		
	N/A	Flare	Traversable L
	N/A	Land	ing Length (in)
Surveyor Notes:	N/A	Land	ing Width (in)
N/A	N/A	Land	ing Slope (%)
	N/A	Land	ing X Slope (%
	N/A	Land	ing Curb? (Y/N
	N/A	Shar	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.5.1	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
	N/A	X Wa	ılk 1 Width (in)
		X Wa	ılk 1 Slope (%)
		X Wa	ılk 1 X Slope (%
	N/A	Ram	p inside XWalk
		Road	Slope (%)



Total Cost:





