

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10018374 Main Street: TRESHAM_CT Cross Street: N/A Location: SW **Severity Score:** Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 869201689452 Ramp Type: Perp 8.75

Codes/Mitigation Info/Possible Solution



Street 1 Name	TRESHAM CT
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Cor
Remove & Replace Entire Ramp.	N/A
	No
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.1	N/A
,	N/A
	N/A
	N/A

Total Cost:	\$ 1850.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	49.0	Yes	Ram	Slope (%)	6.9		
No	Ramp Width (in)	40.0	Yes	Yes Ramp XSlope (%)				
N/A	Flare Type LT	N/A	N/A Flare Type RT			N/A		
N/A	Flare Slope LT (%)	N/A	N/A Flare Slope RT (%)			N/A		
N/A	Flare Traversable LT?	N/A	N/A	N/A Flare Traversable RT?				
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	N/A DWS Contrast?		N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)		N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	То Е		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)		N/A		
	X Walk 1 Slope (%)	5.3		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	3.0		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A		
	Road Slope (%)	3.0	N/A	Clear	Space?	N/A		
	Road X Slope (%)	5.3	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		
1								





