## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31853	ction ID: 31853 Main Street: TIBBLE_CREEK_WY			Cross Street: WATERLEAF_LN				Location:	SE
ADA ID: 869FA142DABA	A Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
and the second	The	Possible Solutions:		Compliance Description			Data Compliance Description		
Contraction of the		Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.7
				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
a la alta				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
TIER	A CAR			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
CERDEN CORES	a state			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
1 Jacob T		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
The BIT				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A Star H				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	17 2001			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
bring and a set	and and the first				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	TIBBLE CREEK WY				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	2.5
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	0.9
Street 2 Name	WATERLEAF LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	1.4	N/A	Clear Space?	N/A
					Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

es Surface Condition? (G/P)

Good

