

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|   |                              |   |                        |
|---|------------------------------|---|------------------------|
| Intersection ID: 44822                  | Main Street: GOLDEN_RIDGE_LN | Cross Street: HIRAM_ST                  | Location: NW           |
| ADA ID: 86AD23A2073F                    | Ramp Type: Perp              | Initial Pass/Fail: Pass                 | Overall Compliance: No |
| Severity Score: 15.25                   |                              |   |                        |
| Codes/Mitigation Info/Possible Solution |                              | Field Measurements/Component Compliance |                        |



Possible Solutions:

**Remove & Replace Entire Ramp.  
Remove & Replace Gutter.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.2.1, R304.2.2-Perp,  
R304.3.2-Para, R305, R304.5.4,  
R304.5.3**

Total Cost: \$ 2600.00

| Compliance | Description           | Data   | Compliance | Description                 | Data |
|------------|-----------------------|--------|------------|-----------------------------|------|
| N/A        | Ramp Length (in)      | 47.0   | Yes        | Ramp Slope (%)              | 6.3  |
| Yes        | Ramp Width (in)       | 48.0   | Yes        | Ramp XSlope (%)             | 4.9  |
| N/A        | Flare Type LT         | Sloped | N/A        | Flare Type RT               | N/A  |
| N/A        | Flare Slope LT (%)    | 1.6    | N/A        | Flare Slope RT (%)          | 8.3  |
| N/A        | Flare Traversable LT? | No     | N/A        | Flare Traversable RT?       | No   |
| No         | Landing Length (in)   | 47.5   | No         | DWS Provided?               | No   |
| Yes        | Landing Width (in)    | 48.0   | N/A        | DWS Contrast?               | No   |
| No         | Landing Slope (%)     | 3.9    | N/A        | DWS Length (in)             | N/A  |
| Yes        | Landing X Slope (%)   | 4.7    | N/A        | DWS Full Width?             | No   |
| N/A        | Landing Curb? (Y/N)   | No     | N/A        | DWS Offset (in)             | N/A  |
| N/A        | Shared Landing?       | No     |            |                             |      |
| Yes        | Gutter Ponding?       | No     | No         | Gutter Slope (%)            | 6.2  |
| Yes        | Gutter Lip Ht (in)    | 0.0    | No         | Gutter X Slope (%)          | 5.2  |
| N/A        | Painted X Walk1?      | No     | N/A        | Painted X Walk2?            | N/A  |
|            | X Walk 1 Direction    | To E   |            | X Walk 2 Direction          | N/A  |
| N/A        | X Walk 1 Width (in)   | N/A    | N/A        | X Walk 2 Width (in)         | N/A  |
|            | X Walk 1 Slope (%)    | 2.4    |            | X Walk 2 Slope (%)          | N/A  |
|            | X Walk 1 X Slope (%)  | 7.6    |            | X Walk 2 X Slope (%)        | N/A  |
| N/A        | Ramp inside XWalk1?   | N/A    | N/A        | Ramp inside XWalk2?         | N/A  |
|            | Road Slope (%)        | N/A    | N/A        | Clear Space?                | Yes  |
|            | Road X Slope (%)      | N/A    | N/A        | Clear Space to XWalk (in)   | N/A  |
| Yes        | Any Obstructions?     | No     | Yes        | Storm Grate/Utility Hazard? | No   |
|            | Obstruction Type      |        |            | Storm Grate/Utility Type    |      |
|            |                       | N/A    |            |                             | N/A  |
|            |                       |        | Yes        | Surface Condition? (G/P)    | Good |

