

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10013227	Main Street: THE_PLAZA	Cross Street: N/A	Location: SE
ADA ID: 86E1E2FF34AE	Ramp Type: Para	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R305.2

Total Cost: \$ 1600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	70.0	N/A	Ramp Length RT (in)	71.0
Yes	Ramp Width LT (in)	84.0	Yes	Ramp Width RT (in)	84.0
Yes	Ramp Slope LT (%)	7.7	Yes	Ramp Slope RT (%)	5.0
Yes	Ramp XSlope LT (%)	0.4	Yes	Ramp XSlope RT (%)	1.7
Yes	Landing Length (in)	84.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	97.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.2	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.4	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	2.5
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.3
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.8
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Replace	Curb Slope (%)	8.6

