

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5567	7 Main Street: JOHN_KIRK_DR			Cross Street: UNIVERSITY_TERRACE_DR				Location:	S	
ADA ID: 86F7887FDD	C Ramp Type: Directional1		In	Initial Pass/Fail: Fail Overall Comp			npliance: No Severity Score:		1.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	~11110	Possible Solutions:		Compliance Description		Data	Data Compliance Description			
and the main the		Remove & Replace Entire I	Ramp.	N/A	Ramp Length (in)	25.0	N/A	Grade Break?	N/A	
	S. A.	•	•	Yes	Ramp Width (in)	71.0	N/A	Grade Break Slope (%)	0.0	
				Yes	Ramp Slope (%)	3.0	N/A	Grade Break XSlope (%)	0.0	
A Ray (1)	19/11/Alto Al			No	Ramp XSlope (%)	2.3				
No. A. S.	6. 1			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
6				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
EST.	ALCONT AND A	Surveyor Notes:		N/A	Flare Traversable LT	? <b>N/A</b>	N/A	Flare Traversable RT?	N/A	
	t.	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
Ser .	CARE DO			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	NY ME THE			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	// white the second			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
1 / / / / / / / / / / / / / / / / / / /		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
1/1/10/12		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
		S		N/A	Painted X Walk1?	No		Road Slope (%)	1.6	
Street 1 Name	UNIVRSITY TERRACE DR				X Walk 1 Direction	To NE		Road X Slope (%)	2.6	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%	) 2.6	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1	? <b>N/A</b>		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost:	\$ 1600	.00	Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	2.5	

