

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13861 Main Street: GANYMEDE_PL Cross Street: HOLLIROSE_DR Location: NW **ADA ID: 86F8AE74E58E** Ramp Type: Directional1 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



GANYMEDE PL Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A R304.5.1, R304.2.2

PROW/ADA: Total Cost: 1600.00

Field Measurements/Component Compliance						
Compliance Description		Data	Compliance		Description	Data
N/A	Ramp Length (in)	57.0	N/A	Grad	e Break?	N/A
No	Ramp Width (in)	46.5	N/A	Grad	e Break Slope (%)	0.0
No	Ramp Slope (%)	14.2	N/A	Grad	e Break XSlope (%)	0.0
Yes	Ramp XSlope (%)	1.9				
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	0.0	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	0.0	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	0.0	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	0.0	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A
N/A	Shared Landing?	N/A	N/A	DWS	Offset RT (in)	N/A
N/A	Gutter Ponding?	0.0	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	2.0	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No		Road	Slope (%)	1.
	X Walk 1 Direction	To S		Road	X Slope (%)	2.0
	X Walk 1 Width (in)	N/A		Clear	Space?	N/A
	X Walk 1 Slope (%)	1.1	N/A	Clear	Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	2.0	N/A	Storn	n Grate/Utility Hazard?	N/A
N/A	Ramp inside XWalk1?	N/A		Storn	n Grate/Utility Type	
N/A	Any Obstructions?	N/A				N/A
	Obstruction Type		Yes	Surfa	ce Condition? (G/P)	Good
		N/A	N/A	Curb	Slope (%)	11.7





