

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43409Main Street:E\_E\_WADDELL\_DRCross Street:NATIONS\_FORD\_RDLocation:NWADA ID: 872D4CDB3855Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:12.5

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name E WADDELL DR
Stop Condition-Street 2 Signal
Street 2 Name NATIONS FORD RD
Stop Condition-Street 1 Signal

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

N/

Surveyor Notes:

N/A

N/

PROW/ADA:

Not Found, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance					
Compliance Description		Data	Comp	oliance Description	Data
N/A	A Ramp Length (in)	109.0	Yes	Ramp Slope (%)	5.2
Ye	s Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.2
N/A	A Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	A Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	A Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	A Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	A Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	<b>A</b> Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	A Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	A Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	A Shared Landing?	N/A			
N/A	A Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	A Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To S		X Walk 2 Direction	To E
N/A	X Walk 1 Width (in)	70.0	N/A	X Walk 2 Width (in)	112.0
	X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	2.1
	X Walk 1 X Slope (%)	2.9		X Walk 2 X Slope (%)	1.8
N/A	A Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
	Road Slope (%)	0.9	N/A	Clear Space?	N/A
	Road X Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A
N/	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





