cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Curb Slope (%)

4.0

Intersection ID: 49276	Main Street: HOMECOMING_WY				Cross Street: REUNION_ST				Location: NE		
ADA ID: 87458A756D0B	Ramp Ty	Ramp Type: Combination1Diag			Initial Pass/Fail: Fail Overall Complian				nce: No Severity Score: 0		
Code		Field Measurements/Component Compliance									
		Possible Solutions:			Compliance Description		Data Compl		liance Description	Data	
	1	Remove & Replace Cur	b Ram	np With	N/A	Ramp Length LT (in)	25.0	N/A	Ramp Length RT (in)	25.0	
	1	Two New Directional Ra			Yes	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	48.0	
		Equivalent.			No	Ramp Slope LT (%)	12.0	No	Ramp Slope RT (%)	9.6	
					Yes	Ramp XSlope LT (%)	0.8	No	Ramp XSlope RT (%)	2.1	
	- in				N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	8.6	
					No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	6.8	
the second second		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
La Bo	the second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
B &	ECOMMO				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
S S	THE DAY				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	Roal	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	last a	R304.5.1, R304.2.2, R30	04.5.3.		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		R304.3.2	,		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	REUNION ST				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	StopSign					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
Stop Condition-Street 2	HOMECOMING WY					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	2.5	
						X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	5.6	
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	6.4		Clear Space?	N/A	
						Road X Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A	
			-			AL -4		N/A	Any Obstruction?	N/A	
									Obstruction Type		
				AL						N/A	
the second				DEL	No.			N/A	Storm Grate/Utility Hazard?	N/A	
				- Thereas	X	21			Storm Grate/Utility Type	n/A	
12				1 At	1					N/A	
					and the second s			Yes	Surface Condition? (G/P)	Good	