

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

9.9

Intersection ID: 10037397	ID: 10037397 Main Street: SCALEYBARK_RD			Street:	N/A	Location:	Е		
ADA ID: 8761594686F1 Ramp Type: Para			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description		Data
BELROSELE		Remove & Replace Entire Ram	n	N/A	Ramp Length LT (in)	76.0	N/A	Ramp Length RT (in)	N/A
	Same Mar		.6.	Yes	Ramp Width LT (in)	55.0		Ramp Width RT (in)	N/A
L.				No	Ramp Slope LT (%)	9.0	N/A	Ramp Slope RT (%)	N/A
	- ARGE I AV			Yes	Ramp XSlope LT (%)	1.3	N/A	Ramp XSlope RT (%)	N/A
Strain 1924	1 344 1 E			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
8 4				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E. 2		N/A		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			1/4
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Contraction PARS	PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	18 .				,			,	
A LANDARD		R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	3.9		X Walk 2 Slope (%)	N/A
Street 1 Name	SCALEYBARK RD				X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	None			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	1600.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

